Work Orde	er ID 8727 53:08 PM	2		*872	772*						Page 1
tem ID: Revision ID:	D412-702-309 Harness Assembly		A	ccept	*N900	<u>0</u> 401	INN	* s	etup Star Stoj	IN	S1*
	7/05/12 S	tart Qty: 5.00 Req'd Qty: 5.00	*5* *5*		Cust Item Customer:	ID:					S2*
Approvals:	Process Plan: QC:		Date://207-/2	Tooling: SPC (Y/N):		ate:		R	kun Star Stoj		R1* R2*
Sequence ID/ Work Center II	D D	peration escription		Set Up/ Run Hours	Tool ID	Tool # 1		Accept Qty	Reject Qty	Reject Number	Insp. Stamp
Draw Nbr	Revisio	on Nbr									
ICAD412-702	REV 4			0.00							
™ *1∩∩*				0.00				SX		•	
Small Fab Small Fab	·	Memo Assemble a	s per dwg ICA D412-702 p.	0.00 49			-				
110	· Q	C5- Inspect part comp	leteness to step on W/O	0.00							-
110 QC Quality Control		Memo		0.00 AS	7/4/70		((5)			
									:		
120				0.00			,)	4	1)
120							,	`S~/	·	(2	17/23
Packaging		Memo	th P/N & CHG# and pack for	0.00 shinning as ner DDD T	M12-702-309						•,
Packaging		CHG001 Location: PPP Rev:	612	simpping as pei PPP L	J+12-102-307						

Viran

									e.					
W/O:			WORK ORDER CHANGES											
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector					
								:						
Part No	:	PAR #:	Fault Category:NC			No DQ	Date:							
		esolution:												
NCR:				ER NON-CONFORMA										
DATE	STEP	Description of NC	Initial	Corrective Action Section	on B	Verific		Approval	Approval					
		Section A	Chief Eng	Action Description Chief Eng	Date	Section C		Chief Eng	QC Inspector					
				so. 4										
,														
		,												
									f					

Work Order ID 87272 July-11-12 12:53:08 PM				*872	72*							Page 2
Revision ID:	D412-702-			Accept	*N900040100)*	Setup	Start Stop		S1* S2*
Start Date: 7/05/12 Start Qty: 5.00 Required Date: 8/10/12 Req'd Qty: 5.00 Reference:		*5* *5*		Cust Item ID: Customer:						ı V.		
Approvals:	Process P	lan:	Date:	Tooling:	D:	ate:	_		Run	Start Stop	*N	R1*
	QC:		Date:	SPC (Y/N):	Date:						*N	R2*
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accep Qty	t Re	*	Reject Number	Insp. Stamp
*130		QC21- Final Inspection	- Work Order Release	0.00						2/	1/24	1 #
QC		Memo		0.00					•	1.	1	' (/

Quality Control

MLJ 1267/23

	•									
W/O:			WO	RK ORDER CHAN	GES	* *			* C	
DATE	STEP	PR	OCEDURE CHAP	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
								•	`	
] } }		
Part No	:	PAR #:	Fault Categ	jory:	NCR: Ye	_ Date: _				
	Res	solution:	Disposition	: `	QA: N/C	Closed: _		Date: _		
NCR:			WORK ORDE	R NON-CONFORM	IANCE (N	CR)				
DATE	STEP	Description of NC	Initial	Corrective Action Se Action Description	ction B		Verification App		Approval	
		Section A	Chief Eng	Chief Eng	Da	ite Sec	tion C	Chief Eng	QC inspector	
						- p				
						1				
<u></u>										
								<u> </u>		
i										
									r	
					·					

July-11-12 12:53:07 PM

Work Order ID:

87272

Parent Item:

D412-702-309

Parent Item Name:

Harness Assembly

Start Date: 7/05/12

Required Date: 8/10/12

Start Qty: 5.00

Required Qty: 5.00

	- ·	> 50 /			T4	-	Unit of	Otrion	Oty nor Vit	T-4-1	04.	Data	Status
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
03573-3		Manufactured	No			100	Each	12.0000	1	5),	1/2/
Adapter									(2.0)		7)—	14	07/
				Location		Loc Oty	Lo	oc Code					/
				GA		12					·	ند به	, ,
				804	185	12				5 //			
D4088-041		Manufactured	No			100	Each	18.0000	1	5	ر سخر	/) .	62
Shoulder Harness									<u> </u>		_/_	//	10-1
				Location		Loc Oty	<u>Lo</u>	oc Code				1	·
				GA		-4					//		
				847	794	18				5.		0 .	
				ST267		22							/
MS24693-S272		Purchased	No			100	Each	253.0000	4	20	///	/)	2 6-1
Screw										*	\mathcal{I}	ـــارك	4041
				Location		Loc Qty	<u>L.</u>	oc Code				•	
				GA		236				 /			
				118	8352	236			_ Ó	<i>20</i>			
				ST288		17				*-m-m			
				110	6391	11							
					6737	2						, ,	
				111	7977	4			· · · · · ·			1	
AN960JD10LL		Purchased	No		:	100	Each	3,432.000	0 4	20	C [) 10	6/07
Washer									· · · · · · · · · · · · · · · · · · ·	<u> </u>			/-//
				Location		Loc Qty	L	oc Code					
				ST337A		3432				2~ /			
				19	085	272			_ ~				

3160

19600

									ν,
W/O:			W	ORK ORDER CHANG	GES				
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
			•						
D4 N-									
Part No		PAR #:							
	Res	solution:	Dispositi	on:	QA: N/C	Closed: _		Date: _	
NCR:			WORK ORI	DER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC			ction B	Verif	ication	Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		n & Sec	tion C	Chief Eng	QC Inspector
						-			
					:				
<u>.</u>									
		•							
			·						

Picklist Print

July-11-12 12:53:07 PM

Page 2

Work Order ID:

87272

Parent Item:

D412-702-309

Parent Item Name:

Harness Assembly

MS21042L3

Nut

Purchased

No

Location

117885

119017

119075 121444

122141

ST300

ST317

100

Loc Oty

1191

32

763 138

258

2000 2000

Each

3,191.0000

Start Qty: 5.00


Start Date: 7/05/12

20


Required Date: 8/10/12
Required Qty. 5.00

Loc Code

	oopaoo								1 .
W/O:			WO	RK ORDER CHANG	ES				
DATE	STEP	PRO	OCEDURE CHAN	IGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
Part No	:	PAR #:	Fault Categ	jory:	NCR: Ye	es No D o	QA:	Date: _	
	Re	solution:	Disposition): <u>`</u>	_ QA: N/C	Closed: _		Date: _	
NCR:			WORK ORDE	R NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC Section A	Initial	Action Description		n& ∣ _{Se}	fication ction C	Approval Chief Eng	Approval QC Inspector
			Chief Eng	Chief Eng	Da	ite	 .		,
									:



<u>DETAIL 'K' D412-702-101A/-103A/-105A/-107A/-109A/-115A/-117A AND D412-702-101B/-106B/-105B/-107B/-109B/-115B/-117B OR -301/-303/-305/-307/-309/-315/-317 HARNESS ASSEMBLIES</u>



DETAIL 'L' D412-702-111A/-111B/-113A/-113B OR -311/-313/-321/-323 HARNESS ASSEMBLIES

COPYRIGHT © 2004 BY DART AEROSPACE LTD. ◆

THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

			DQA	4 :			
NCR: Yes / No	WORK ORDER NON-CO	WORK ORDER NON-CONFORMANCE / UPDATE					
Work Order:	DISPOSITION	AG/	AINST DEPARTMEN	IT/PROCESS			
work order.	Rework	Skid-tube Cros	stube	Water			

								<u> </u>		QA Closed:	Date):	
Work Order	r:				DISPOSITION		AGAINST DEPARTMENT/PROCESS						
Part No				Rework Scrap Use-as-is Work Order Update	T	Skid-tube Crosstube Machining Small Fab Thermoforming Finishing Large Fab Composite				Water Jet d. Eng. Coor. re/Packaging Supplier	Engineering Quality Other		
Root				Descri	ption of work order update	Initi	ial	Action	T	Sign &			•
Cause	Date	Step	Qty	. (or Non-conformance	Chief	Eng	Description		Date	Verification	QC Inspector	
Doc/Data Equip/Tooling Operator Material Setup Other Process Supplier Training				,)						•
Unapproved		<u> </u>	11			AULT C	ATE	GORY	!		1		
Landing	g Gear				General								•
Bending Centre Not Concentric to O/S Cracks Crushed/Crimped. Cuffs Heat Treat Inspection Strip in Tube Ripples in Bend Torque Waves in Extrusion		Bend BOM/Route Broken/Damaged Burrs Contamination Countersink Cut Too Short Drill Holes Drawing	Ha Ins Ins Mi Mi Mi	struct ainte islabe isread fset	ion Incomplete ions Incomplete/Unclear enance eled		Ovalized Over/Under Part Incorre Part Lost/M Part Moved Positioned \ Power Loss/	ct issing Wrong	Pressure/Forced Temperature/Cure Weld Wrong Stock Pulled Other	-			
	Turning S	•			Finish	Ou	it of S	Sequence					
	Wave/Twist in Tube				Folio	Ou	Outside Dimensions						

H:/FORMS/Quality Assurance\approved QA/NCRWO Rev G